acilities Invento	rv						
=CI #	Priority	Description		Comments	Year to Complete	Completion Date	
1	High	Southwest gym door blocked by sidewalk*	\$1,000.00	May need ground down, may not be ADA compliant in the summer		*resolved with 8/23 door repair?	
1	Medium	Emergency safety lock down switch/magnetic door stops	\$15,000.00	Can be for threat and fire safety			
2	Low	Cracks in walls	\$1,000.00	Repair settling cracks in walls			
2	Low	Old building demo	\$100,000.00	Old building past its usefulness, not worth fixing			
3	Low	Security of food prep area	\$1,000.00	Locks on door and an overhead roller for counter			
3	Medium	Fire extinguishers behind doors	\$500.00	Several fire extinguishers are behind doors if opened/ access			
3	Low	Asbestos- old building removal	\$80,000.00	Asbestos makes the old building hard to maintain/ fix			
3	High	Woodchips on Playground	\$825.00	Systematic addition of woodchips	Continuing	10/22	
	Medium	Handicap parking spot	\$500 00	Need to define a Handicap parking spot			

4	High	Flood precaution	\$2,000.00	Measures taken to limit water damage from Camp Creek overflow			
4	High	Shed Roofs over exterior doors	\$3,000.00	To combat weather- heating, cooling, snow piling			
5	Low	Seal adjustment on exterior doors	\$500.00	Exterior doors may need adjustment to ensure proper sealing			
5	Medium	LED upgrades	\$4,000.00	LED efficient upgrades	Continuing	2020	
5	Low	Heat vents in Hallway	\$3,000.00	Currently no heat into hallway, fire hazard to leave doors open			
6	Low	Baseball field and dugouts	\$2,000.00	Aging components need upgrading		8/22- Sign replac	ed
7	Low	Special Education room	\$	Space needed for SpEd opportunities/ materials as we grow			
7	High	Additional classroom space for growing needs	\$	Classroom space as community grows			
2	Med/High	Stairs to the old building		Cement crumbling			
1	Medium	Parking Lot Lighting		South end of the south parking lot is very dark			

3,7	High	Completion of unfinished classroom				
2	Low	Trees	Pruning		8/23	
4	Low	Trees	Replanting	Continuing	2 trees donated/planted 8/23	
6	Medium	Exterior painting of building				
2,7	Medium	Doors & Enclosure for double entrance- Gym, Maintenance room	Or improve overall entrance		Doors repaired 8/23; enclosure being planned	
2	high	Roof Leak	Water running down and through west facing window and pooling on counter in west facing third grade classroom		Resealled shingles 11/23; monitor in case it needs further attention	
	Medium	North entry to new building: key FOB access				
1,3	Medium	Ramp access to enter old building				
2	Medium	Painting of Gym Exterior				
			Reviewed and approved on: March 14, 2024			
FCI#	1	Safety				
	2	Damage/Wear Out				
	3	Code/Standards				

4	Energy Conservation	
	Environmental Improvements	
6	Aesthetics	
7	Building Enhancements	